

FIG. 1A




FIG. 1B





FIG. 2B

FIG. 3A




FIG. 3B




FIG. 4A





FIG. 4B







Fig. 5



F16, 6

FIG. 7A






FIG. 7B







FIGURE 8








FIGURE 9



(PRIOR ART)






FIG. 11



$f_1$  90° out of phase with  $f_2$

FIG. 12

1216



F16, 13

$f_1 90^\circ$  out of phase with  $f_2$




Fig. 14